

**OFFICE OF THE SENIOR MANAGER (MECH)-II**  
**ORISSA CONSTRUCTION CORPORATION LIMITED**  
**MACHINERY BANK PROJECT**

GOPABANDHU NAGAR, UNIT-VIII, BHUBANESWAR-12.

**No.OCC/MBP-II/107:04/1073(WE).**

**Dt.12.12.2011.**

**SHORT QUOTATION CALL NOTICE- 09/11-12**

Sealed quotations are invited from repairer for repair of Backhoe Loader OR-01N-3509 make ACE as per scope of work. The quotations will be received up to 3 Pm of dt.19.12.2011 and will be opened on the same day by 4 Pm in the office of the undersigned in the presence of the quotationer or his authorized representatives. Copy of PAN CARD and Registered Certificate should be submitted along with the quotations. The undersigned reserves the right to accept or reject any or all quotations without assigning any reason there off.

Encl:- As above.

**Senior Manager (Mech)-II**

**Memo No. \_\_\_\_\_/OCC/MBP-II/107:04**

**Dt. \_\_\_\_\_/**

Copy submitted to the General Manager (Mech), OCC Ltd., Gopabandhu Nagar, BBSR for favour of kind information and necessary action.

Encl:- As above

**Senior Manager (Mech)-II**

**Memo No. \_\_\_\_\_/OCC/MBP-II/107:04**

**Dt. \_\_\_\_\_/**

Copy submitted to the Financial Adviser & Chief Accounts Officer, OCC Ltd., Gopabandhu Nagar, BBSR for favour of kind information and necessary action.

Encl:- As above

**Senior Manager (Mech)-II**

**Memo No. \_\_\_\_\_/OCC/MBP-II/107:04**

**Dt. \_\_\_\_\_/**

Copy submitted to the Senior Manager, OCC Ltd., System Business Division. Gopabandhu Nagar, BBSR for information. He is requested to host the above quotation call notice in the website of OCCL,

Encl:- As above

**Senior Manager (Mech)-II**

**Memo No. \_\_\_\_\_/OCC/MBP-II/107:04**

**Dt. \_\_\_\_\_/**

Copy to the Notice Board, OCC Ltd., Machinery Bank Project-II, Gopabandhu Nagar, BBSR / Notice Board of Head office, OCC Ltd., Unit-8, Gopabandhu Nagar, BBSR.

Encl:- As above

Copy to – Guird File

**Senior Manager (Mech)-II**

Scope of work:-

<b><u>Sl.No.</u></b>	<b><u>Description of work</u></b>
1.	King pin opening, Overhauling & refitting.
2.	Tie rod end bend portion straightening.
3.	Front hub bearing greasing 2 Nos.
4.	Accelerator cable change.
5.	Re-building cutting bucket face & Loader bucket by 10mm m.s. plate. Strengthen the both side of the bucket.
6.	Battery box straightening & welding.
7.	Hydraulic oil change.
8.	Silencer manifold opening, broken bolt opening, manifold refitting.
9.	King pin bush fitting & rimming by lathe machine.
10.	Tie rod bush fitting & rimming 2 Nos. by lathe.
11.	Front axle opening, bush changing & rimming.
12.	“O” pin opening, polishing, Greasing & Fitting.
13.	Spindle oil seal shat polishing- 2Nos.
14.	Hub bearing sheet reconditioning by metal filling & machining.

**Senior Manager (Mech)-II**